These are the update instructions for the Raptor M40 version 1.04 firmware update.

Version numbers associated with this release:

	M40
Firmware	1.04
Software	1.0.0.11

Firmware updaters require the mouse be plugged directly into the PC, rather than into an external USB hub port or a USB extension cable. For best results, please ensure your device is plugged into a USB 2.0 or USB 1.1 port before running the firmware update utility.

The firmware updater will erase all existing settings on the product and reset it to factory defaults. The firmware updater will erase all existing settings on the product and reset it to factory defaults.

<table>
<tr><td>
</td><td>When the firmware updater is launched, it will first display a warning dialog. Make sure not to unplug the mouse or turn off or reboot the computer during the update process.

Once the firmware update program launches, click “Update Firmware” to start the firmware update process.

* Images to the left will reflect the devices version of firmware you are installing.</td></tr>
<tr><td>
</td><td>Once the firmware update process is complete, click “Exit” to close the updater.

*Images to the left will reflect the devices version of firmware you are installing.</td></tr>
</table>

Significant known issues:

- Firmware updaters require the mouse be plugged directly into the PC, rather than into an external USB hub port or a USB extension cable.

- For best results, please ensure your device is plugged into a USB 2.0 or USB 1.1 port before running the firmware update utility.

M40 UI 1.0.0.11 fixes

M40	Issue
V	Fix mouse removal detection
V	Fix model name in dialog boxes to M40
V	Fix “Assign Buttons” “Button Options” [+] button allows adding empty selections, if no selection [+] now grayed out
V	Fix “Assign Buttons” “Button Options” Left, Right, Middle, Forward, Back, Scroll Up, Scroll Down assignment and fix make/break code sending upon button press/release

M40 FW 1.04 fixes

M40	Issue
V	Fix HW playback when starting new macro could get repeating key add key break to prevent that
V	Fix save backlight status in mouse. Changing backlight , new setting is now saved in mouse
V	Improve sensor SROM handling, make more robust